

PROJECT : Total Fitness, Chester

Client

Total Fitness

Contractor:

D&D, Winsford

Materials & Inspection:

Approved Delvemade Distributor

Products Used:

SEAMSIL[®] for cut edge corrosion

DELCOTE[®] for roof recoating

Specification:

Seamsil[®] has been specified and used to secure the long term performance of the roof at the Chester Total Fitness Centre with a roof makeover with Seamsil[®] the UK's leading Cut Edge Corrosion Treatment.

During the last 3 years, seventeen of the famous physical fitness centres have benefitted from the application of Seamsil[®], part of a time proven remedial system for the external repair of profiled steel roof sheeting.

The problem was cut edge corrosion. It can be caused by a combination of poor installation techniques and on-site cutting plus attack from acid rain and pollutants, which are then retained as moisture in critical roof overlaps and gutter overhangs. This results in corrosion of the profiled steel roof sheets. If not treated quickly and effectively, the damage could lead to the need for partial or complete roof replacement.



Telephone: + 44 (0)1204 868604

Email: contact@delvemade.com

www.delvemade.co.uk

PERFORMANCE COATINGS

Manufactured by

Delvemade

Specify Delvemade products by name • Seamsil • Delcote • Delcote GS • Delglaze

